

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/19/2018

Submitted Date:

03/23/2018

Document Number:

678301573**FIELD INSPECTION FORM**Loc ID 318405 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
LARA-MESA, SUSANA	303-825-4822	cogcc@kpk.com	VP OF ENGINEER

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241237	WELL	PR	12/13/1976	OW	123-09025	DITLEV-SIMONSEN C 3	EI

General Comment:

well inspection along with sampling of water in excavation approximately 550 feet west of Ditlev-Simonsen C 3 wel.
Sampling done with Ms. Lara-Mesa of Kauffman at site and she collected spilt samples.

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Pipeline sign crossing utility easement to west of well is not legible as shown in photo attached. Pipeline appears to run between Ditlev-Simonsen C 3 and Ditlev-Simonsen B 1. location of illegible sign is approx. 550 feet west of Ditlev-Simonsen C 3 well location.		
Corrective Action:	Install legible marker per rule 1102	Date:	04/23/2018
Type	WELLHEAD		
Comment:	wellhead sign is faded but legible will need to be repaired or replaced in near future.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	#		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	241237	Type:	WELL	API Number:	123-09025	Status:	PR	Insp. Status:	EI
Complaint									
Comment:	Complaint 200444807 regarding petroleum hydrocarbons in soil at excavation near north-south trending sewer line. Excavation reportedly was done as part of investigation of possible gas leak to surface detected by contracto for operator. Excavation sampling COENV database facility number is 757228.								
Corrective Action:								Date:	

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: Other _____ Comment: trench COENV facility # 757228

Sample	Sample Type: GROUND WATER
Time: _____ (MM/dd/yyyy hh:mm)	GPS: Lat _____ Long _____
BTEX: YES _____ TPH: _____ Anion: _____	Captions: _____ General Chemistry: _____
Dissolved Methane: _____ Composition: _____	Stable Isotopes: _____ 8260: _____
8270: _____ RCRA Metals: _____	910-Metals: _____ PAH: _____
Other: _____	
Comment: delivered to lab on 19 March 2018, split samples collect at same time by Ms. Lara-Mesa of KPK	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678301574	pipeline	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4412631