

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/07/2018

Submitted Date:

03/19/2018

Document Number:

688800013

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
325672 \_\_\_\_\_ Hughes, Jim \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96735  
Name of Operator: WILLIFORD RESOURCES, L.L.C.  
Address: 6506 S LEWIS AVE STE 102  
City: TULSA State: OK Zip: 74136

**Findings:**

- 16 Number of Comments  
4 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Callahan, Linda	918-749-8828	lcallahan3@swbell.net	<a href="#">SW Inspection Reports</a>
Stevens, Glenn	970-749-0192	glennstevens@centurylink.net	<a href="#">SW Inspection Reports</a>
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215209	WELL	PR	05/28/2003	OW	067-06814	PAYNE-SCHMITT 1	EI

**General Comment:**

On March 7, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Williford Resources LLC Payne-Schmitt #1. For the most recent field inspection report of this facility, please refer to document #685302174.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Tanks are labeled with contents and capacity and have NFPA placards.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Free standing sign located near pump jack.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Free standing sign near ASTs.		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	Valve	<= 1 bbl	
Comment:	Stained soil beneath valves on ASTs.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>04/19/2018</u>
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	Area beneath prime mover is wet and stained.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>04/19/2018</u>
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	Well head is wet with fluids and area surrounding well head is stained.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>04/19/2018</u>
In Containment: No			
Comment:			
<input checked="" type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Guard fencing.		
Corrective Action:			Date:

<b>Equipment:</b>		corrective date
Type: Other	# 2	
Comment:	55 gal. drums in secondary containment.	
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:		
Corrective Action:		Date:
Type: Flow Line	# 1	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	Drop out tanks for gas supply lines.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	OTHER	STEEL AST		37.146178,-108.103341
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	210 bbl.
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Berms are weathered and trampled by cows. Capacity does not appear to be adequate.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.1.			Date: 04/19/2018

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
------	--

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 215209 Type: WELL API Number: 067-06814 Status: PR Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	55 gal. drums in secondary containment.

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On March 7, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Williford Resources LLC Payne-Schmitt #1. For the most recent field inspection report of this facility, please refer to document #685302174.</p> <p>During this inspection it was noted that the location has recently been dragged. Stained soil has been dispersed across the location.</p> <p>The well head is leaking fluids and the ground surrounding the well head is stained.</p> <p>The prime mover is leaking and the ground underneath is wet and stained.</p> <p>The valves on the ASTs are leaking and the ground underneath them is stained.</p> <p>The secondary containment berm appears to be inadequate for the capacity of the tanks.</p>	hughesj	03/19/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401578868	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4406873">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4406873</a>
688800014	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4406835">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4406835</a>