

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2018

Submitted Date:

03/27/2018

Document Number:

689401083**FIELD INSPECTION FORM**

Loc ID 312573 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES, INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|----------------------------|------------------------------------|
| Lujan, Carlos | | carlos.lujan@state.co.us | |
| Reid, Jordan | (970) 563-4000 | maralextechjr@gmail.com | All Inspections |
| Browning, Chuck | | chuck.browning@state.co.us | |
| Hartman, Robert | (970) 244-3041 | bhartman@blm.gov | Petroleum Engineer |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 221938 | WELL | SI | 10/01/2017 | GW | 077-08540 | FEDERAL 13-1 | SI |

General Comment:

[This is a follow up inspection to FIR Doc#675200527. Any corrective actions not addressed from previous inspections are still applicable.](#)

LocationOverall Good: ☒

| | | | |
|----------------------|--------------------------------------|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Incomplete sign at wellhead. | | |
| Corrective Action: | Install sign to comply with Rule 210 | Date: | 05/27/2018 |

Emergency Contact Number:

Comment: Posted Emergency Contact Number 1-970-858-8550

Corrective Action:

Date:

Overall Good: ☐

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Fencing/: | | | |
| Type | PIT | | |
| Comment: | Wire mesh fence falling into pit. Noted on previous inspection. See Pit section. | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|--|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 221938 | Type: | WELL | API Number: | 077-08540 | Status: | SI | Insp. Status: | SI |
| Idle Well | | | | | | | | | |
| Purpose: <input type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____ | | | | | | | | | |
| Comment: <div>Last production on file was from Sept 2017.</div> | | | | | | | | | |
| Corrective Action: <div></div> Date: _____ | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NOPit ID: Lat: 39.359010Long: -108.498690Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: c**Fencing:**Fencing Type: LivestockFencing Condition: InadequateComment: Fence is falling down. Corrective action has not been met from previous inspection.Corrective Action: Date: 10/15/2014**Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: No pit permit on fileCorrective Action: Date: 04/11/2018**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------|---|
| 689401084 | LATHAM 13-1 Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4415502 |