

# Inspection Photos

API: 05-067-06911

Operator: BP AMERICA PRODUCTION  
COMPANY

Inspection Date: 3/7/2018



**Photo 1. View of the project area from the northwestern corner facing center.**



**Photo 2. View of the western portion of the interim reclamation area from the northwestern corner facing southward. Kochia debris scattered on well pad and along project boundaries needs removal.**





**Photo 3. View of the northern portion of the working area from the northwestern corner facing eastward. Grasses such as sand dropseed (*Sporobolus cryptandrus*) are established along the outer boundaries of the project area.**



**Photo 4. View of the northern portion of the project area, outside of fenced working area, facing westward.**