


## Inspection Photos

Location Name: KAMMERZELL-65N66W 29NWNW

Location #: 329854



Kammerzell 29-4 H6 wellhead facing W.



Kammerzell 29-4 H6 wellhead facing S. Casing head has audible leak with stain. Master valve stem appears to be dripping fluid



## Inspection Photos

Location Name: KAMMERZELL-65N66W 29NWNW

Location #: 329854




Kammerzell 29-5 well facing N.



Tank Battery facing SE. Berms appear inadequate for containment.



Inspection Photos  
Location Name: KAMMERZELL-65N66W 29NWNW  
Location #: 329854



Separator facing S.

**Corrective Action: unused equipment & trash.**

**Wet stains on dump lines.**

