

Location			
Lease Road:			
Type	Main		
comment:	Adequate		
Corrective ActionL			Date:
Type	Access		
comment:	Access road to Kammerzell 29-5 well is adequate		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	TRASH		
Comment:	Already addressed in CA on inspection document #691200035.		
Corrective Action:			Date:
Type	UNUSED EQUIPMENT		
Comment:	Already addressed in CA on inspection document #691200035.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel fence around Kammerzell 29-5 wellhead.		
Corrective Action:			Date:
Equipment:			
Type:	Horizontal Heated Separator	# 1	corrective date
Comment:	Commingles Kammerzell 29-4H6 & 29-5 wells.		
Corrective Action:			Date:
Type:	Plunger Lift	# 1	
Comment:	Kammerzell 29-5		
Corrective Action:			Date:
Type:	Bird Protectors	# 2	
Comment:			
Corrective Action:			Date:

Type: Gas Meter Run	# 2	
Comment:	E. Gas Meter Run not in use.	
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:	30" ECD - Tank VOC's, pilot is on.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	48 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms capacity appears inadequate. Shares berms with 2 produced oil tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.372425,-104.812457
Comment:	Oil tanks are connected near top with an equalizer line. Currently shut.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms capacity appears inadequate. Shares berms with produced H2O vault.			
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 250136 Type: WELL API Number: 123-17939 Status: SI Insp. Status: SI

Producing Well

Comment: Unmarked header at separator inlet is closed. Valves at well are open for production. Please confirm production or SI status.

Corrective Action:

Date:

BradenHead

Comment: Bradenhead appears to be plumbed to surface.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200038	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4415852