

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/02/2018

Submitted Date:

03/21/2018

Document Number:

681700997

**FIELD INSPECTION FORM**

Loc ID 454039 Inspector Name: Arauza, Steven On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 15550  
Name of Operator: CHAMPLIN PETROLEUM COMPANY  
Address: P O BOX 1330  
City: HOUSTON State: TX Zip: 77251

**Findings:**

- 10 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Axelson, John		john.axelson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454039	LOCATION	AC	02/13/2018		-	Boxer Water Plant	EI

**General Comment:**

[COGCC Environmental inspection to document field conditions at former Boxer Water Plant.](#)

**Location**

**Lease Road:**

Type	Access				
comment:	Two-track access road remaining south of modular steel ASTs. See photos.				
Corrective Action				Date:	

Overall Good:

Emergency Contact Number:

Comment:					
Corrective Action:				Date:	

**Good Housekeeping:**

Type	WEEDS				
Comment:	Site-wide uncontrolled weeds. See photos.				
Corrective Action:				Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#				corrective date
Flow Line	# 2				
Comment:	NOT IN USE: Two (2) forty-foot flowline risers located ~130' SW of ASTs. See photos.				
Corrective Action:				Date:	
Ancillary equipment	# 1				
Comment:	Water plant consists of multiple flowline risers located at modular ASTs. See photos.				
Corrective Action:				Date:	
Ancillary equipment	# 1				
Comment:	Additional equipment located ~100' west of modular ASTs. See photos.				
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	2	OTHER	STEEL AST		,	
Comment:	Two (2) modular steel ASTs on location. See photos.					
Corrective Action:				Date:		

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: No berm				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 454039 Type: LOCATION API Number: - Status: AC Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No Stormwater Best Management Practices were observed on inspection date.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: _____	Other: _____	Length: _____	Width: _____	

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date:   

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment:

[Approximately 45'x25' devegetated area located 90' south of modular ASTs overlying what appears to be former skim pit in historical aerial photos dating from 1989 to 8/18/2011. Aerial photos also document 110'x110' pit immediately south of former skim pit area. Both pits appear to have been abandoned and reseeded between 8/18/2011 and 9/17/2012 Google Earth Aerials. See attached.](#)

Corrective Action

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401582263	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4409871">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4409871</a>
681700998	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4409862">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4409862</a>
681700999	2005 Aerial - shows pits clearly	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4409863">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4409863</a>
681701000	2011 Aerial - last aerial showing open pits	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4409864">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4409864</a>
681701001	2012 Aerial - first aerial showing closed pits	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4409865">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4409865</a>