

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/27/2018

Submitted Date:

03/28/2018

Document Number:

691300073**FIELD INSPECTION FORM**

Loc ID 332839 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam	970-420-0536	Adam.Kraich@state.co.us	(Area 117) Field Operations
,		COGCCInspections@extracti onog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296130	WELL	PR	03/03/2011	GW	123-25897	BALLFIELD Y6 7-7-31	PR
296131	WELL	PR	03/03/2011	GW	123-25896	FARMERS Y7 6-6-31	PR
296270	WELL	PR	09/02/2009	GW	123-26712	COMMONS Z2 2-2-6	PR
418146	WELL	PR	12/17/2010	GW	123-31835	MAIN Y3 6-8-31	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Shared rod iron around wellheads

Corrective Action:

Date:

Equipment:

corrective date

Type: Plunger Lift

4

Comment: All wells on location run plunger lift.

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 296130 Type: WELL API Number: 123-25897 Status: PR Insp. Status: PR**Producing Well**Comment: PRWell flows to battery#435366

Corrective Action:

Date:

Facility ID: 296131 Type: WELL API Number: 123-25896 Status: PR Insp. Status: PR**Producing Well**Comment: PRWell flows to battery#435366

Corrective Action:

Date:

Facility ID: 296270 Type: WELL API Number: 123-26712 Status: PR Insp. Status: PR**Producing Well**Comment: PRWell flows to battery#435366

Corrective Action:

Date:

Facility ID: 418146 Type: WELL API Number: 123-31835 Status: PR Insp. Status: PR**Producing Well**Comment: PRWell flows to battery#435366

Corrective Action:

Date:

COGCC Comments

Comment

All wells flow to battery#435366All tanks and surface equipment are identified on the LaSalle Directional Project 2 (332840) inspection form. See document#69130069 for details.

User

kraicha

Date

03/28/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691300074	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4416448