

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/19/2018

Submitted Date:

03/23/2018

Document Number:

678301573

FIELD INSPECTION FORM

Loc ID 318405 Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: K P KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
LARA-MESA, SUSANA	303-825-4822	cogcc@kpk.com	VP OF ENGINEER

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241237	WELL	PR	12/13/1976	OW	123-09025	DITLEV-SIMONSEN C 3	EI

General Comment:

well inspection along with sampling of water in excavation approximately 550 feet west of Ditlev-Simonsen C 3 wel.
Sampling done with Ms. Lara-Mesa of Kauffman at site and she collected spilt samples.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Pipeline sign crossing utility easement to west of well is not legible as shown in photo attached. Pipeline appears to run between Ditlev-Simonsen C 3 and Ditlev-Simonsen B 1. location of illegible sign is approx. 550 feet west of Ditlev-Simonsen C 3 well location.		
Corrective Action:	Install legible marker per rule 1102	Date:	04/23/2018
Type	WELLHEAD		
Comment:	wellhead sign is faded but legible will need to be repaired or replaced in near future.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Pump Jack	#		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241237 Type: WELL API Number: 123-09025 Status: PR Insp. Status: EI

Complaint

Comment: [Complaint 200444807 regarding petroleum hydrocarbons in soil at excavation near north-south trending sewer line. Excavation reportedly was done as part of investigation of possible gas leak to surface detected by contracto for operator. Excavation sampling COENV database facility number is 757228.](#)

Corrective Action:

Date:

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: Other Comment: trench COENV facility # 757228

Sample	Sample Type: <u>GROUND WATER</u>			
Time: _____	(MM/dd/yyyy hh:mm)	GPS: Lat _____	Long _____	
BTEX: <u>YES</u>	TPH: _____	Anion: _____	Captions: _____	General Chemistry: _____
Dissolved Methane: _____	Composition: _____	Stable Isotopes: _____	8260: _____	
8270: _____	RCRA Metals: _____	910-Metals: _____	PAH: _____	
Other: _____				
Comment: <u>delivered to lab on 19 March 2018, split samples collect at same time by Ms. Lara-Mesa of KPK</u>				

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401585463	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4412645
678301574	pipeline	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4412631