



**Environmental**

**Spills/Releases:**

Type of Spill: PRODUCED WATER Estimated Spill Volume: \_\_\_\_\_

Comment: Follow up to site inspection of 12/18/17. TPH-contaminated pit spoils are being landfarmed under approved REM 10464. Landfarm is 100% bermed with soil lift ~18 inches. Trackhoe is on site and material has been amended w manure and re-tilled. Small stockpile (<75cy) has also been mixed w manure. Pit remains open. Staining and odor is minimal vs 12/18 when soils were heavily stained w strong petroleum odor.

Corrective Action: Continue O&M of landfarm and pit cleanup operations including scheduled tillage until confirmation soil samples from landfarm, pit, and other soils are Table 910-1 compliant. Recycle treated soils for beneficial re-use as backfill or other approved placement. Date: 12/31/2018

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401585408	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4412590">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4412590</a>
690300232	Insp Photos 3-21-18	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4412542">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4412542</a>