

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/29/2018

Submitted Date:

03/29/2018

Document Number:

690001258**FIELD INSPECTION FORM**
 Loc ID 302455 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10604Name of Operator: COMPLETE ENERGY SERVICES INCAddress: 4727 GAILLARDIA PKWY STE 250City: OKLAHOMA CITY State: OK Zip: 73142**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Travis Sellmer		tsellmer@hpdswd.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159270	UIC DISPOSAL	AC	04/27/2009		-	HPD PLATTEVILLE 1	AC
298847	WELL	IJ	04/12/2012	DSPW	123-29168	HPD PLATTEVILLE 1	AC

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Disposal Facility		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Frac tank mentioned in previous inspection has been removed.		
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Well contained within shed		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	Electric Motor 500 HP		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric Motor 450 HP		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	1000 BBLS	STEEL AST		40.216921,-104.719660
Comment:					
Corrective Action:					
	Date:				

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Concrete	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:		Date:				
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	OTHER	STEEL AST		,	
Comment:						
Corrective Action:		Date:				
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity) 750 Bbl						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:		Shared with 1000 Bbl Tank				
Corrective Action:		Date:				
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	6	OTHER	STEEL AST		,	
Comment:						
Corrective Action:		Date:				
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity) 750 Bbl						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:		Shared with 1000 Bbl Tank				
Corrective Action:		Date:				
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:		Date:				
<u>Flaring:</u>						
Type	Ignitor/Combustor					

Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 159270 Type: UIC API Number: - Status: AC Insp. Status: ACFacility ID: 298847 Type: WELL API Number: 123-29168 Status: IJ Insp. Status: AC**Underground Injection Control**UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: 1427UIC RoutineInj./Tube: Pressure or inches of Hg 1412 Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
(e.g. 30 psig or -30" Hg) Inj Zone: ACGMITC: Pressure or inches of Hg 0 Previous Test Pressure \_\_\_\_\_ Last MIT: 06/13/2014Brhd: Pressure or inches of Hg 0 Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_Comment: Units are PSI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: PUMP FEED

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Routine inspection. Previous MIT date: 6/13/14 Frac tank mentioned in previous inspection has been removed Spill related repairs and soil removal have been accomplished.	carlilec	03/29/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690001259	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419684">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419684</a>