



Inspection Photos  
Location Name: CROW POINT 34-18  
Facility ID # 127469




Photo 3. Stained soil around prime mover



Photo 4. No tank capacity posted on tank

Inspection Photos  
Location Name: CROW POINT 34-18  
Facility ID # 127469



**Photo 5. No tank capacity posted on tank**