



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unmarked/ riser one has no valve or plug		
Corrective Action:	Comply with Rule 603.f .	Date:	04/29/2018

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 282391 Type: WELL API Number: 071-08670 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Last MIT OCT. of 2013 will need MIT this year.

Corrective Action:  Date:

**BradenHead**

Comment: Plumbed to surface

Corrective Action:  Date:

Facility ID: 282392 Type: WELL API Number: 071-08671 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment:

Corrective Action:  Date:

**BradenHead**

Comment: Plumbed to surface

Corrective Action:  Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat: 37.279430      Long: -104.836590

Reference Point: SE      Other: \_\_\_\_\_      Length: 50      Width: 30

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: c

**Fencing:**

Fencing Type: Livestock      Fencing Condition: Adequate

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_      Oil Accumulation: \_\_\_\_\_      2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Type: Produced Water      Lined: NO      Pit ID:      Lat: 37.279660      Long: -104.836340

Reference Point: SE      Other: \_\_\_\_\_      Length: 50      Width: 30

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: c

**Fencing:**

Fencing Type: Livestock      Fencing Condition: Adequate

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:				Date:
Corrective Action				
Anchor Trench Present:		Oil Accumulation:	2+ feet Freeboard:	
Comment:				Date:
Corrective Action				
Permit:	Facility ID	Permit Num	Expiration Date	
	285211	1395522		
	285210	1395521		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691400092	LOC PICS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4421082">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4421082</a>