

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2018

Submitted Date:

03/30/2018

Document Number:

691400126**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 308394      Beardslee, Tom      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING      State: TX      Zip: 75039**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Precup, Jim		james.precup@state.co.us	
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	<a href="#">All Inspections</a>
Duran, John		john.duran@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270857	WELL	PR	03/21/2004	GW	071-07967	DUNLOP 44-19	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Deadman # &amp; Marked

# 4

Comment:

Corrective Action:

Date:

Type: Progressive Cavity

# 1

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

Type: Vertical Separator

# 1

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	270857	Type:	WELL	API Number:	071-07967	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:								Date:	
BradenHead									
Comment:		Plumbed to surface							
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID:

Lat: 37.151790Long: -104.705790Reference Point: SE

Other: \_\_\_\_\_

Length: 80Width: 60**Lining:**

Liner Type:

Liner Condition:

Comment: No freeboard marker

Corrective Action

Date: c**Fencing:**Fencing Type: None

Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

Permit:	Facility ID	Permit Num	Expiration Date
	274256	12230355	

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691400127	LOC PICS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4421099">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4421099</a>