

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2018

Submitted Date:

03/30/2018

Document Number:

691400132**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 309098 Beardslee, Tom 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections
Precup, Jim		james.precup@state.co.us	
Duran, John		john.duran@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288033	WELL	PR	03/24/2007	GW	071-09077	PATIENT 42-31	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Prime Mover

1

Comment: Corrective Action: Date:

Type: Progressive Cavity

1

Comment: Corrective Action: Date:

Type: Vertical Separator

1

Comment: Corrective Action: Date:

Type: Gas Meter Run

1

Comment: Corrective Action: Date:

Type: Deadman # & Marked

4

Comment: Corrective Action: Date:

Type: Compressor

1

Comment: Corrective Action: Date: **Venting:**

Yes/No NO

Comment: Corrective Action: Date: **Flaring:**

Type

Comment: Corrective Action: Date:

Inspected Facilities									
Facility ID:	288033	Type:	WELL	API Number:	071-09077	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:								Date:	
BradenHead									
Comment:		Plumbed to surface							
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: YES

Pit ID:

Lat: 37.130340Long: -104.704590Reference Point: SE

Other: _____

Length: 80Width: 40**Lining:**Liner Type: PVCLiner Condition: Adequate

Comment:

Sun is creating cracks in liner outside of pit walls. Liner needs to be addressed soon.

Corrective Action

Date: c**Fencing:**Fencing Type: LivestockFencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

Permit:	Facility ID	Permit Num	Expiration Date
	301103	1941955	

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
691400133	LOC PICS	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4421102