

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/31/2018

Submitted Date:

03/31/2018

Document Number:

688400122

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
308183 _____ Gomez, Jason _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10084
Name of Operator: PIONEER NATURAL RESOURCES USA INC
Address: 5205 N O'CONNOR BLVD STE 200
City: IRVING State: TX Zip: 75039

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections
Kosola, Jason		jason.kosola@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Duran, John		john.duran@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263850	WELL	PR	09/17/2005	GW	071-07640	BEAN 33-26	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PIT		
Comment:	BARB WIRE		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 263850 Type: WELL API Number: 071-07640 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
		Culverts	Pass			
		Ditches	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: YES Pit ID: Lat: 37.140500 Long: -104.852360

Reference Point: SE Other: _____ Length: 28 Width: 17

Lining:

Liner Type: Plastic Liner Condition: Inadequate

Comment: No liner or liner not maintained LINER HAS HOLE AND TEARS SEE ATTACHED PHOTOS

Corrective Action: Lack of pit liner or pit liner compromised (Rule 904). IMMEDIATE NOTIFICATION TO THE OPERATOR Reduce fluid level in pit, contact COGCC EPS staff for directives.

Date: 04/03/2018c

Fencing:

Fencing Type: Other Fencing Condition: Adequate

Comment: 4' BARB WIRE

Corrective Action:

Date: _____

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action:

Date: _____

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Comment:

Corrective Action:

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688400123	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4421222