

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/21/2018

Submitted Date:

03/26/2018

Document Number:

690300234

**FIELD INSPECTION FORM**

Loc ID 322352 Inspector Name: Spencer, Stan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

**Findings:**

- 1 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Lujan, Carlos		carlos.lujan@state.co.us	
Gifford, Adriane		a.gifford@chevron.com	
Fischer, Alex		alex.fischer@state.co.us	
,		regulatory@foundationenergy.com	
Conklin, Curtis		curtis.conklin@state.co.us	

**General Comment:**

*(This area is intentionally left blank for general comments.)*

**Environmental**

**Spills/Releases:**

Type of Spill: PRODUCED WATER Estimated Spill Volume: \_\_\_\_\_

Comment: Followup to Pit 111760 closure. Pit was closed under REM 5249 issued to Chevron (former operator) of location now operated by Foundation. REM pre-dated eForm and was closed by F-4 #401568705. A single monitoring well remains on location and has been Table 910-1 compliant for > one year.

Corrective Action: Plug and abandon monitoring well in compliance with CDWR criteria. Well is disconnected and listed as TA since at least 10/2016. This inspection only addressed the REM and does not include other potential necessary corrective actions. Date: 04/30/2018

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401587226	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4414181">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4414181</a>
690300236	Foundation-Chevron 045-06103 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4414180">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4414180</a>