

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/26/2018

Submitted Date:

03/27/2018

Document Number:

691200037

**FIELD INSPECTION FORM**

Loc ID 329855 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10459  
Name of Operator: EXTRACTION OIL & GAS INC  
Address: 370 17TH STREET SUITE 5300  
City: DENVER State: CO Zip: 80202

**Findings:**

- 15 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Precup, Jim		james.precup@state.co.us	
,		COGCCInspections@extracti onog.com	<a href="#">All Inspections inc 8 North, 7 North, XPR</a>
Gomez, Jason		jason.gomez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250136	WELL	SI	12/01/2017	GW	123-17939	KAMMERZELL 29-5	SI

**General Comment:**

*(This area is currently blank for general comments.)*

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access road to Kammerzell 29-5 well is adequate		
Corrective ActionL			Date:
Type	Main		
comment:	Adequate		
Corrective ActionL			Date:

Overall Good:

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Already addressed in CA on inspection document #691200035.		
Corrective Action:			Date:
Type	TRASH		
Comment:	Already addressed in CA on inspection document #691200035.		
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel fence around Kammerzell 29-5 wellhead.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type:	Horizontal Heated Separator	# 1	
Comment:	Commingles Kammerzell 29-4H6 & 29-5 wells.		
Corrective Action:			Date:
Type:	Gas Meter Run	# 2	
Comment:	E. Gas Meter Run not in use.		
Corrective Action:			Date:
Type:	Emission Control Device	# 1	
Comment:	30" ECD - Tank VOC's, pilot is on.		
Corrective Action:			Date:

Type: Plunger Lift	# 1		
Comment:	Kammerzell 29-5		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	48 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms capacity appears inadequate. Shares berms with 2 produced oil tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.372425,-104.812457
Comment:	Oil tanks are connected near top with an equalizer line. Currently shut.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms capacity appears inadequate. Shares berms with produced H2O vault.			
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 250136 Type: WELL API Number: 123-17939 Status: SI Insp. Status: SI

**Producing Well**

Comment: Unmarked header at separator inlet is closed. Valves at well are open for production. Please confirm production or SI status.

Corrective Action:

Date:

**BradenHead**

Comment: Bradenhead appears to be plumbed to surface.

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401588814	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4415855">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4415855</a>
691200038	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4415852">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4415852</a>