

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2018

Submitted Date:

04/02/2018

Document Number:

690300243**FIELD INSPECTION FORM**
 Loc ID 335875 Inspector Name: Spencer, Stan On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name          | Phone        | Email                                 | Comment                  |
|-----------------------|--------------|---------------------------------------|--------------------------|
| Inspection, Terra TEP | 970-285-9377 | COGCCInspectionReports@terraep.com    |                          |
| Lujan, Carlos         |              | carlos.lujan@state.co.us              |                          |
| Janicek, Jake         |              | COGCC.inspections@caerusoilandgas.com | All Piceance inspections |
| Fischer, Alex         |              | alex.fischer@state.co.us              |                          |

**General Comment:**

Inspection prior to water share approval between TEP and Caerus. Wells to be completed using shared water include 13 former Marathon DUCs drilled in 2008. Wells are within corrugated steel cellars. ASTS in poly-lined steel SPCC. Weather is 35 degrees and snow. Roads muddy. One reported spill on location of pw from separator was closed 2015.

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 401594506    | INSPECTION SUBMITTED        | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4422214">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4422214</a> |
| 690300243    | INSPECTION APPROVED         | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4422597">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4422597</a> |
| 690300244    | Location 335875 insp photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4422211">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4422211</a> |