

Inspection Photos
Location Name: Hotchkiss Federal 1289 #18-31
API: 05-051-06071



Hotchkiss Federal 1289 #18-31 well head and pump.



Oil drain to 55 gal. drum in secondary containment.

Inspection Photos
Location Name: Hotchkiss Federal 1289 #18-31
API: 05-051-06071



Vertical separator with produced water line.



Antifreeze leak under generator engine.