

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2018

Submitted Date:

03/27/2018

Document Number:

691200035**FIELD INSPECTION FORM**Loc ID 329854 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@extracti onog.com	All Inspections inc 8 North, 7 North, XPR
Precup, Jim		james.precup@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250135	WELL	SI	12/01/2017	GW	123-17938	KAMMERZELL 29-4H6	PR

General Comment:

Location			
Lease Road:			
Type	Main		
comment:	Adequate		
Corrective Action	L	Date:	
Type	Access		
comment:	Kammerzell 29-4H6 well access road is adequate		
Corrective Action	L	Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Current sign at Kammerzell 29-4H6 well is accurate correcting the CA from previous inspection conducted on 12/8/2017 (DOC #689300470).		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			
Date: _____			
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Found multiple unused fittings near separator dump lines.		
Corrective Action:	Statewide unused equipment, weeds, waste, and trash requirements. Comply with Rule 603.f .		Date: 04/30/2018
Type	TRASH		
Comment:	Found large rag on ground near separator volume pot.		
Corrective Action:	Statewide unused equipment, weeds, waste, and trash requirements. Comply with Rule 603.f .		Date: 04/11/2018
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel fence around Kammerzell 29-4H6 wellhead.		
Corrective Action:		Date:	
Equipment:			
Type: Gas Meter Run		# 2	corrective date
Comment:		E. Gas Meter Run not in use.	

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Commingles Kammerzell 29-4H6 & 29-5 wells.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	30" ECD - Tank VOC's, pilot is on.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Kammerzell 29-4H6		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	48 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms capacity appears inadequate. Shares berms with 2 produced oil tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.372425,-104.812457
Comment:	Oil tanks are connected near top with an equalizer line. Currently shut.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Berms capacity appears inadequate. Shares berms with produced H2O vault.				
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 250135 Type: WELL API Number: 123-17938 Status: SI Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadComment: Bradenhead is plumbed to surface.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401588813	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4415854
691200036	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4415851