

Inspection Photos
Location Name: DGU Hotchkiss Federal 1289 #18-H2
API: 05-051-06104



DGU Hotchkiss Federal 1289 #18-H2 well head and ancillary equipment.



Location ID #427218 production equipment.

Inspection Photos

Location Name: DGU Hotchkiss Federal 1289 #18-H2

API: 05-051-06104



DGU Federal 1289 #18-CS1 and CS2 wells.



Stainless tubing on chemical injection system at DGU Hotchkiss Federal 1289 #18-H1 leak.



Inspection Photos

Location Name: DGU Hotchkiss Federal 1289 #18-H2

API: 05-051-06104



Location ID #427218 tank battery.



Unused risers spray painted.