

Inspection Photos

API: 05-067-07874

Operator: BP AMERICA PRODUCTION
COMPANY

Inspection Date: 3/7/2018



Photo 1. View of the project area from the northern corner facing center.



Photo 2. View of the northeastern portion of the interim reclamation area from the northern corner facing southeastward. Revegetation is progressing with sand dropseed (*Sporobolus cryptandrus*), intermediate wheatgrass (*Thinopyron intermedium*), smooth brome (*Bromus inermis*), as well as rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3. View of the northwestern portion of the interim reclamation area from the northern corner facing southwestward.



Photo 4. View of the southwestern cut-slope from the southern corner facing northwestward.



Photo 5. View of erosion occurring along the eastern edge of the well pad where stormwater flows from the well pad into a drainage. Stormwater controls are placed here, but additional stabilization is needed.



Photo 6. View of stormwater controls in the northeastern portion of the project area, that are filling with sediment and need maintenance.