

# Inspection Photos

API: 05-067-08885

Operator: BP AMERICA PRODUCTION  
COMPANY

Inspection Date: 3/21/2018



**Photo 1. View of the northern portion of the project area from the northwestern corner facing eastward.**



**Photo 2. View of the western portion of the interim reclamation area from the northwestern corner facing southward. Revegetation is progressing with sand dropseed (*Sporobolus cryptandrus*), intermediate wheatgrass (*Thinopyron intermedium*), and western wheatgrass (*Pascopyrum smithii*).**



**Photo 3. View of the eastern portion of the interim reclamation area from the northern corner facing southwestward.**



**Photo 4. View of erosional tunneling that is starting to occur within the northern fill slope.**



**Photo 5. View of erosional channeling in the southern cut-slope Stabilization measures are needed here.**