

# Inspection Photos

API: 05-067-07855

Operator: BP AMERICA PRODUCTION  
COMPANY

Inspection Date: 3/21/2018



**Photo 1. View of the project area from the northeastern corner facing center. Erosion controls are in place and appear to be functioning.**



**Photo 2. View of the eastern portion of the interim reclamation area from the northeastern corner facing southward. Revegetation is progressing with western wheatgrass (*Pascopyrum smithii*) and smooth brome (*Bromus inermis*).**



**Photo 3. View of the northern portion of the interim reclamation area from the northeastern corner facing westward.**



**Photo 4. View of the southern portion of the project area from the southeastern corner facing westward.**



**Photo 5. View of the western portion of the project area from the southwestern corner facing northward.**



**Photo 6. View of erosion controls in the western project area, appear to be functioning at this time.**