

Inspection Photos

API: 05-067-08752

Operator: BP AMERICA PRODUCTION
COMPANY

Inspection Date: 3/21/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the eastern portion of the interim reclamation area from the northwestern corner facing southward. Revegetation is progressing with western wheatgrass (*Pascopyrum smithii*) and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3. View of the northern portion of the interim reclamation area from the northwestern corner facing eastward.



Photo 4. View of the southern portion of the project area from the southwestern corner facing eastward.