

Inspection Photos

API: 05-067-08285

Operator: BP AMERICA PRODUCTION
COMPANY

Inspection Date: 3/21/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the eastern portion of the interim reclamation area from the southeastern corner facing northward. Revegetation is progressing with irrigated grasses, not in identifiable form.



Photo 3. View of the southern portion of the project area from the southeastern corner facing westward.



Photo 4. View of the southwestern portion of the project area from the southwestern corner facing northward.