

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/28/2018

Submitted Date:

04/04/2018

Document Number:

688800033

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
Hughes, Jim \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10515  
 Name of Operator: GUNNISON ENERGY LLC  
 Address: 1801 BROADWAY #1200  
 City: DENVER State: CO Zip: 80202

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Robinson, Brad	(970) 929-5122	brad.robinson@oxbow.com	President
McWilliams, Dan	(970) 986-2927	dan.mcwilliams@oxbow.com	
Roy, Catherine		catherine.roy@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451553	SPILL OR RELEASE	CL	08/17/2017		-	Deadman Gulch Unit	EI

**General Comment:**

On March 28, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gunnison Energy LLC Spill/Release Point ID #451553. For the most recent field inspection report of this facility, please refer to document #680602316. This field inspection was conducted to determine the progress of Remediation Project #10395.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type LOCATION

Comment: [Post and wire fencing around perimeter of project area.](#)

Corrective Action:

Date:

Type OTHER

Comment: [Steel barricade around pipeline risers.](#)

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Other

# 2

Comment: [Water and gas pipeline risers.](#)

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 451553 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	In Process					
Blankets	Pass					
Slope Roughening	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
On March 28, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gunnison Energy LLC Spill/Release Point ID #451553. For the most recent field inspection report of this facility, please refer to document #680602316. This field inspection was conducted to determine the progress of Remediation Project #10395. The project area is fenced and covered with straw erosion control blankets. Wattles along the eastern edge of the project area have been destroyed and/or require maintenance.	hughesj	04/04/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800034	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424529">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424529</a>