

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/15/2017

Submitted Date:

04/04/2018

Document Number:

686000108

FIELD INSPECTION FORM

Loc ID 307125 Inspector Name: SUTPHIN, DIRK On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10149

Name of Operator: DEINES* JON E DBA DEINES MAZZA PARTNERSHIP

Address: 901 N COUNTY RD 21

City: BERTHOUD State: CO Zip: 80513

General Comment:

2017 Flowline NTO Inspection

COGCC Comments

Comment	User	Date
<u>Met with landowner. This is a domestic gas well. Flowline (1" black heavy duty wire wrapped hose) is disconnected. Water dropout container 100' NE next to wire fence line. He may be interested in having the well plugged.</u>	<u>sutphind</u>	<u>04/04/2018</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
<u>401596793</u>	<u>INSPECTION SUBMITTED</u>	<u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424543</u>
<u>686000109</u>	<u>Well looking SW</u>	<u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424525</u>
<u>686000110</u>	<u>Well sign</u>	<u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424526</u>
<u>686000111</u>	<u>Well looking north</u>	<u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424527</u>
<u>686000112</u>	<u>Water dropout looking NE</u>	<u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424528</u>