

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2017

Submitted Date:

04/04/2018

Document Number:

686000113**FIELD INSPECTION FORM**Loc ID 319854 Inspector Name: SUTPHIN, DIRK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 18795Name of Operator: COLTON LIMITED LIABILITY COAddress: 475 17TH STREET #1200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**General Comment:**[2017 Flowline NTO Inspection](#)

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

\_\_\_\_\_

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Met operator on location. Observed flowline abandonment on the Green #1 with Vic Behrens directing the work. They had 2 excavations open. One was for the buried concrete produced water vault and the other was at the location where the separator was, where the riser came up for the well to separator flowline. What smelled to me like hydrocarbon contaminated soils were encountered in both excavations. This is based on grab samples from the soils that were dug out and piled on surface next to the excavations. Groundwater was encountered in the bottom of the separator excavation. I commented to Vic that someone should be documenting the soil removal and extent of the apparent spill. Ryan Dornbos <ryan@petersonenergyoperating.com> responded to me 6/13/17. He submitted a Form 27 on behalf of Colton LLC for the removal of the PW vault removed from the Green #1 Battery.	sutphind	04/04/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401596977	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424769">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424769</a>
686000114	Separator flowline riser	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424762">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424762</a>
686000115	Produced water vault	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424763">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424763</a>