

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/15/2017

Submitted Date:

04/04/2018

Document Number:

686000103

FIELD INSPECTION FORM

Loc ID 424350 Inspector Name: SUTPHIN, DIRK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10544
Name of Operator: HIGHPOINT ENERGY LLC
Address: 361 71ST AVE
City: GREELEY State: CO Zip: 80634

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

General Comment:

[2017 Flowline NTO Inspection](#)

COGCC Comments

Comment	User	Date
Met operator on location. Tank Battery, Separators, Combustors, 11 Wells. Witnessed operator perform flowline test on one well. All risers not connected to equipment need to be marked with orange paint.	sutphind	04/04/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401596735	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424475
686000103	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4425034
686000104	Site looking NE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424460
686000105	Site looking East	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424461
686000106	Separators looking NW	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424462
686000107	392 Ventures 22JD Well looking SW	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424463