

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/06/2018

Submitted Date:

04/03/2018

Document Number:

688000144

**FIELD INSPECTION FORM**

Loc ID 312286 Inspector Name: YOUNG, ROB On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 95620  
Name of Operator: WESTERN OPERATING COMPANY  
Address: 1165 DELAWARE STREET #200  
City: DENVER State: CO Zip: 80204

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
James, Steven	(303) 893-2438	steve@westernoperating.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
112001	PIT	AC			-	STATE 11-16	EI

**General Comment:**

[Environmental inspection related to Pit Facility ID 112001 closure per Rem #9966.](#)

**Inspected Facilities**

Facility ID: 112001 Type: PIT API Number: - Status: AC Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water                  Lined: NO                  Pit ID: 112001                  Lat: 40.664423                  Long: -103.428593

Reference Point: \_\_\_\_\_                  Other: \_\_\_\_\_                  Length: \_\_\_\_\_                  Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_                  Liner Condition: \_\_\_\_\_

Comment: Pit closed per Rem #9966.

Corrective Action

Date: c

**Fencing:**

Fencing Type: \_\_\_\_\_                  Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_                  Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_                  Oil Accumulation: \_\_\_\_\_                  2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401596017	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4423848">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4423848</a>
688000144	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4425041">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4425041</a>
688000145	Location photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4423838">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4423838</a>