

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2018

Submitted Date:

04/03/2018

Document Number:

688800025**FIELD INSPECTION FORM**Loc ID 427218 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10515Name of Operator: GUNNISON ENERGY LLCAddress: 1801 BROADWAY #1200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
McWilliams, Dan	(970) 986-2927	dan.mcwilliams@oxbow.com	
Fischer, Alex		alex.fischer@state.co.us	
Robinson, Brad	(970) 929-5122	brad.robinson@oxbow.com	President

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427223	WELL	PR	08/12/2013	GW	051-06103	DGU Hotchkiss Federal 1289 18-H1	EI
427241	WELL	PR	11/15/2012	GW	051-06104	DGU Hotchkiss Federal 1289 18-H2	EI
436613	WELL	WO	08/21/2014	LO	051-06124	DGU Federal 1289 18-CS2	EI
436614	WELL	WO	08/13/2014	LO	051-06125	DGU Federal 1289 18-CS1	EI

General Comment:

On March 28, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gunnison Energy LLC DGU Hotchkiss Federal 1289 #18-H2. For the most recent field inspection report of this facility, please refer to document #689400749.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Signs mounted to stock panel enclosures around well heads.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tanks have NFPA placards and are labeled with capacity and contents.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Posted on location signs.

Corrective Action:

Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel enclosures around well heads.		
Corrective Action:		Date:	

Equipment:					corrective date
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 3				
Comment:	Chemical injection systems				
Corrective Action:				Date:	
Type: Bird Protectors	# 7				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heater Treater	# 2				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	HEATED STEEL AST		39.016779,-107.378321	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Lined steel secondary containment structure.				
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:	Date:		

Flaring:

Type			
Comment:			
Corrective Action:	Date:		

Inspected Facilities

Facility ID: <u>427223</u>	Type: <u>WELL</u>	API Number: <u>051-06103</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>427241</u>	Type: <u>WELL</u>	API Number: <u>051-06104</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>436613</u>	Type: <u>WELL</u>	API Number: <u>051-06124</u>	Status: <u>WO</u>	Insp. Status: <u>EI</u>
Facility ID: <u>436614</u>	Type: <u>WELL</u>	API Number: <u>051-06125</u>	Status: <u>WO</u>	Insp. Status: <u>EI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for chemical systems.
Berms	Pass					
Sediment Traps	Pass					
Ditches	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On March 28, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gunnison Energy LLC DGU Hotchkiss Federal 1289 #18-H2. For the most recent field inspection report of this facility, please refer to document #689400749.	hughesj	04/03/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401595601	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4423369
688800027	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4423361