

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/29/2018

Submitted Date:

04/05/2018

Document Number:

688800045**FIELD INSPECTION FORM**Loc ID 324472 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		inspection@sginterests.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275739	WELL	XX	01/27/2018	GW	051-06060	Federal 11-90-26 1	EI

General Comment:

On March 29, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests Federal 11-90-26 #1. For the most recent field inspection report of this facility, please refer to document #689400572.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign mounted to perimeter fence near separator.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Post and wire fencing.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Post and wire perimeter fencing.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Stock panel fencing was disassembled at the time of this inspection.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	Pump jack was dismantled at the time of this inspection.		
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 1		
Comment:	Pump house.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Engine has been removed from pumping unit.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Generator and electrical supply panel.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	400 BBLs	HEATED STEEL AST		39.074822,-107.408341	
Comment:						
Corrective Action:						Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
		Date:		

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	275739	Type:	WELL	API Number:	051-06060	Status:	XX	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for engine oil container.
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On March 29, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests Federal 11-90-26 #1. For the most recent field inspection report of this facility, please refer to document #689400572. Stock panel fencing and pump jack were disassembled at the time of this inspection. The second produced water AST has peeling paint and rust present.	hughesj	04/05/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800046	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4426077