

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/02/2018

Submitted Date:

04/02/2018

Document Number:

689300771**FIELD INSPECTION FORM**

Loc ID 334952 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Elsener, Garrett	(303)-565-4600	COGCC.inspections@caerusoilandgas.com	all Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268222	WELL	PR	11/29/2004	GW	045-09246	HMU 10-4D(F10)	PR
268224	WELL	PR	05/28/2004	GW	045-09247	HMU 10-3D (F10W)	PR
268225	WELL	PR	01/07/2008	GW	045-09248	HMU 10-6D (F10W)	PR
268226	WELL	PR	11/29/2004	GW	045-09249	HMU 10-5D (F10W)	PR

General Comment:[Routine General Field Inspection](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-800-791-7691

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	WEEDS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Horse Panels around Wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities						
Facility ID:	268222	Type:	WELL	API Number: 045-09246	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Well Producing on plunger lift Last production numbers posted as of Oct. 2017					
Corrective Action:						Date:
Facility ID:	268224	Type:	WELL	API Number: 045-09247	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Well Producing on plunger lift Last production numbers posted as of Oct. 2017					
Corrective Action:						Date:
Facility ID:	268225	Type:	WELL	API Number: 045-09248	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Well Producing on plunger lift Last production numbers posted as of Oct. 2017					
Corrective Action:						Date:
Facility ID:	268226	Type:	WELL	API Number: 045-09249	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Well Producing on plunger lift Last production numbers posted as of Oct. 2017					
Corrective Action:						Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						

Comment: [Rutted Location](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689300772	DocNum: 689300772.4/2/18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4426677