

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/05/2018

Submitted Date:

04/05/2018

Document Number:

689701249**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
335417 \_\_\_\_\_ LONGWORTH, MIKE \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: PO BOX 370  
 City: PARACHUTE State: CO Zip: 81635

**Findings:**

5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Spencer, Stan		stan.spencer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272615	WELL	PR	12/18/2005	GW	045-10104	FEDERAL PA 41-32	PR
272616	WELL	PR	12/12/2005	GW	045-10105	FEDERAL PA 341-32	PR

**General Comment:**

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Bird Protectors	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		

Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)	80 bbls				
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:				
				Date:

**Flaring:**

Type				
Comment:				
Corrective Action:				
				Date:

**Inspected Facilities**

Facility ID: 272615 Type: WELL API Number: 045-10104 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 272616 Type: WELL API Number: 045-10105 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Compaction	Pass			
		Culverts	Pass			
Gravel	Pass					
Compaction	Pass					
Ditches	Fail					

Comment: Ditch behind separator and tank has sediment build up.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689701250	Inspection 689701249 photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4427023">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4427023</a>