

Inspection Photos
Location Name: Behring #23-7
Location: 332096



Photo 1: Wellhead, looking SE



Photo 2: Location, looking E

Inspection Photos
Location Name: Behring #23-7
Location: 332096



Photo from prior inspection for comparison



Photo 3: Stained soil removed

Inspection Photos
Location Name: Behring #23-7
Location: 332096



Photo from prior inspection for comparison



Photo 4: Weeds removed

Inspection Photos
Location Name: Behring #23-7
Location: 332096



Photo from prior inspection for comparison



Photo 5: Tank is covered, labeled

Inspection Photos
Location Name: Behring #23-7
Location: 332096



Photo from prior inspection for comparison



Photo 6: Stained soil removed

Inspection Photos
Location Name: Behring #23-7
Location: 332096



Photo from prior inspection for comparison



Photo 7: Stained soil at riser.

Inspection Photos
Location Name: Behring #23-7
Location: 332096



Photo from prior inspection for comparison



Photo 8: Stained soil at loadout

Inspection Photos
Location Name: Behring #23-7
Location: 332096



Photo from prior inspection for comparison



Photo 9: Stained soil at loadout.

Inspection Photos
Location Name: Behring #23-7
Location: 332096



Photo from prior inspection for comparison



Photo 10: Stained soil at loadout.

Inspection Photos
Location Name: Behring #23-7
Location: 332096



Photo from prior inspection for comparison



Photo 11: Berms built up.

Inspection Photos
Location Name: Behring #23-7
Location: 332096



Photo 12: No screen on stack



Photo 13: Screen on ground, near treater

Inspection Photos
Location Name: Behring #23-7
Location: 332096



Photo 14: Riser near treater