

Inspection Photos
Location Name: Hendershot #1
Location ID: 317497



Photo 1: Location, looking N



Photo 2: Wellhead, looking W

Inspection Photos
Location Name: Hendershot #1
Location ID: 317497



Photo from prior inspection for comparison



Photo 3: Stained soil in engine house

Inspection Photos
Location Name: Hendershot #1
Location ID: 317497



Photo from prior inspection for comparison



Photo 4: Unused pipe at wellhead

Inspection Photos
Location Name: Hendershot #1
Location ID: 317497



Photo from prior inspection for comparison



Photo 5: Gap under netting

Inspection Photos
Location Name: Hendershot #1
Location ID: 317497



Photo from prior inspection for comparison



Photo 6: Weeds in pit

Inspection Photos
Location Name: Hendershot #1
Location ID: 317497



Photo from prior inspection for comparison



Photo 7: Burrows in berms

Location ID: 317497



Photo from prior inspection for comparison



Photo 8: Unused equipment at manifold

Inspection Photos
Location Name: Hendershot #1
Location ID: 317497



Photo from prior inspection for comparison



Photo 9: Stained soil at vessel

Inspection Photos
Location Name: Hendershot #1
Location ID: 317497



Photo from prior inspection for comparison



Photo 10: Wildlife egress