

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2018

Submitted Date:

04/06/2018

Document Number:

690100425**FIELD INSPECTION FORM**Loc ID 320332 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lloyd, Bill		blloyd@petrosharecorp.com	
Brown, Devin	(303)-349-0302	dbrown@petrosharecorp.com	
Powell, Harold	(918)-774-3120	hpowell@petrosharecorp.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203466	WELL	SI	09/01/2017	GW	001-09025	SELTZER G U 2-4	EG

**General Comment:**Followup inspection conducted in response to FIR doc #690100363 dated 02/02/2018; Actions Required have been completed.  
Photos uploaded can be accessed via link(s) at end of report.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused flowline riser observed at wellhead has been removed; Horizontal separator has been removed; Unused tubing & poly pipe has been removed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0	OTHER	STEEL AST		,	
Comment:	Unused crude oil tank (160 bbls) has been removed from location.					
Corrective Action:					Date:	

**Paint**

Condition	<input type="text"/>	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 203466 Type: WELL API Number: 001-09025 Status: SI Insp. Status: EG

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Form 6 intent to abandon doc #401374151 remains in draft status. Note COA outlined by COGCC Engineering staff: As-built GPS doesn't match satellite view. Please obtain new as-built GPS for subsequent 6.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Flowline**

#1	Type: Well Site	1 of Lines
----	-----------------	------------

**Flowline Description**

Flowline Type: Well Site Size: 2" Material: Carbon Steel  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: Multiphase

**Integrity Summary**

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

**Pressure Testing**

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

**COGCC Rules(check all that apply)**

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: This well is Temporarily Abandoned; The flowline riser has been removed at wellhead since Field Inspection Doc #690100363 was performed on 02/02/2018. The off location gas meter has been locked out/ tagged out (by Anadarko). The flowline riser at gas meter is scheduled to be removed (per conversation with Harold Powell on 4/4/18).

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100427	Wellhead and signage	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4427207">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4427207</a>
690100428	Equipment removed (view NE from wellhead)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4427208">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4427208</a>
690100429	Battery Removed ( view NW from wellhead)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4427209">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4427209</a>
690100432	Offsite flowline riser at gas meter	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4427210">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4427210</a>
690100433	Gas meter run locked out/ tagged out	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4427211">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4427211</a>