

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/08/2018

Submitted Date:

04/08/2018

Document Number:

689300840**FIELD INSPECTION FORM**
 Loc ID 335076 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:19 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270355	WELL	PR	05/11/2004	GW	045-09533	CLOUGH RWF 322-29	PR
270359	WELL	PR	05/11/2004	GW	045-09532	CLOUGH RWF 22-29	PR
280050	WELL	PR	04/02/2006	GW	045-11162	CLOUGH RWF 522-29	PR
280051	WELL	PR	03/27/2006	GW	045-11163	CLOUGH RWF 21-29	PR
280052	WELL	PR	02/13/2006	GW	045-11164	CLOUGH RWF 422-29	PR
280053	WELL	PR	04/02/2006	GW	045-11165	CLOUGH RWF 423-29	PR
280054	WELL	PR	03/27/2006	GW	045-11166	CLOUGH RWF 23-29	PR
288284	WELL	PR	12/08/2006	GW	045-13183	CLOUGH RWF 512-29	PR
288285	WELL	PR	12/08/2006	GW	045-13182	CLOUGH RWF 412-29	PR
288286	WELL	PR	12/08/2006	GW	045-13181	CLOUGH RWF 312-29	PR

General Comment:[Routine Field Inspection](#)

Location**Lease Road:**

Type	Access		
comment:	Rutted lease road		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	1-970-285-9377	
Corrective Action:		Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	WEEDS		
Comment:			
Corrective Action:		Date:	
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panel fencing		
Corrective Action:		Date:	

Type	WELLHEAD		
Comment:	Hog panel fencing		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panel fencing		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Faded signage on chemical totes.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:	Date:			

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	270355	Type:	WELL	API Number:	045-09533	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	270359	Type:	WELL	API Number:	045-09532	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	280050	Type:	WELL	API Number:	045-11162	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	280051	Type:	WELL	API Number:	045-11163	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	280052	Type:	WELL	API Number:	045-11164	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	280053	Type:	WELL	API Number:	045-11165	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	280054	Type:	WELL	API Number:	045-11166	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	288284	Type:	WELL	API Number:	045-13183	Status:	PR	Insp. Status:	PR

<u>Producing Well</u>									
Comment:	Well Producing on plunger lift								
Corrective Action:		Date:							
Facility ID:	288285	Type:	WELL	API Number:	045-13182	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Well Producing on plunger lift								
Corrective Action:		Date:							
Facility ID:	288286	Type:	WELL	API Number:	045-13181	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Well Producing on plunger lift								
Corrective Action:		Date:							

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Compaction		Paving				

Comment: [Rutted lease road](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689300841	DocNum: 689300840.4/8/18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4428226