

Interim Reclamation Inspection

April 5, 2018

Operator: CRESTONE PEAK RESOURCES OPERATING LLC- #10633

Location ID: 435070

Inspection Document #: 682403449

Weld County, CO

SWNW Section 19 T3N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070



Photo 1. Photo taken from the eastern location on December 19, 2017, facing South. Interim reclamation areas are not reflective of reference area vegetative levels. Kochia (*Kochia scoparia*) is the dominate vegetative growth throughout the southern interim reclamation area. Some portions appear to be mowed while other portions have not been controlled.



Photo 2. Photo taken from the eastern location on April 5, 2018, facing North. Appears the Operator has mowed Kochia since the previous inspection. Does not appear the Operator has performed the other required interim reclamation activities due on or before April 30, 2018.

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070



Photo 3. Photo taken from the southeastern location on December 19, 2017, facing South. See comments under Photo 1.



Photo 4. Photo taken from the southeastern location on April 5, 2018, facing South. See comments under Photo 2.

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070



Photo 5. Photo taken from the southeastern location on December 19, 2017, facing West. See comments under Photo 1.



Photo 6. Photo taken from the southeastern location on April 5, 2018, facing West. See comments under Photo 2.

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070



Photo 7. Photo taken from the southwestern location on December 19, 2017, facing East. See comments under Photo 1.



Photo 8. Photo taken from the southwestern location on April 5, 2018, facing East. See comments under Photo 2.

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070



Photo 9. Photo taken from the southwestern location on April 5, 2018, facing Northwest. Photo illustrates the lack of desirable germination establishment which is not reflective of reference areas. See Photo 14 of a reference area vegetative photo.

Inspection Photos

Location Name: BOHRER /19H-E168

Location ID: 435070



Photo 10. Photo taken from the southwestern location on April 5, 2018, facing West. See comments under Photo 9.

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070



Photo 11. Photo taken from the southwest location on April 5, 2018, facing West. See comments under Photo 9.

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070



Photo 12. Photo taken from the southwest location on April 5, 2018, facing North. See comments under Photo 9.

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070



Photo 13. Photo taken from the central location on April 5, 2018, facing South. See comments under Photo 9.

Inspection Photos
Location Name: BOHRER /19H-E168
Location ID: 435070




Photo 14. Reference photo taken from the western location on April 5, 2018, facing North. Photo illustrates that interim areas are not reflective of reference area vegetation.