

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2018

Submitted Date:

04/09/2018

Document Number:

690001325**FIELD INSPECTION FORM**

Loc ID 446412 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	<a href="#">All Inspections</a>
Kane, Susan	(720) 946-6700	susan@emdllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446895	TANK BATTERY	AC	07/22/2016		-	ACCORD/CHADBURN #1 O SA 36149584	AC

**General Comment:**

**Inspected Facilities**Facility ID: 446895 Type: TANK API Number: - Status: AC Insp. Status: AC**COGCC Comments**

Comment	User	Date
Former battery location. Battery had served API 05-123-15440 which has been plugged. Riser remains on location (GPS info in photos).	carlilec	04/09/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690001326	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4428378">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4428378</a>