

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/04/2018

Submitted Date:

04/09/2018

Document Number:

690100431**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 318383 \_\_\_\_\_ Maclaren, Joe \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 46290Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Jacobson, Eric		eric.jacobson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241196	WELL	PR	08/01/2017	GW	123-08984	UPRR 43 PAN AM I 25	EG

**General Comment:**

Flowline inspection performed; COGCC Engineering Integrity staff is waiting on the final submittal of flowline NTO data for this well.

**Inspected Facilities**

Facility ID: 241196 Type: WELL API Number: 123-08984 Status: PR Insp. Status: EG

**Flowline**

#1	Type: Non-Well Site	1 of Lines
----	---------------------	------------

Flowline Description

Flowline Type: Non-Well Site Size: Material:

Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:

Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☒ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: The existing flowline has been marked (pin flagged) and runs North in direction; this flowline has failed a pressure test and is scheduled to be re-routed/ replaced. KP Kauffman is in process of installing a new off location flowline from the wellhead, routed south in direction. Approximately 150 linear feet of flowline trench has been excavated; however, it is unclear where the endpoint (tie in) of this flowline is to be located.

Corrective Action: Date:

**COGCC Comments**

Comment	User	Date
Note: Abandon all flowlines in compliance with COGCC rule 1105	maclarej	04/09/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100442	Wellhead, signage and open trench	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4428386">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4428386</a>
690100443	Existing flowline marked w pin flags (view to North)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4428387">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4428387</a>
690100444	Current terminus of flowline trench	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4428388">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4428388</a>