

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401604341

Date Received:

04/11/2018

FIR RESOLUTION FORM

Overall Status: BOTH

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

1 CA Completed

1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Lindsey Rider

970-285-2711

lrider@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680102838

Inspection Date: 03/29/2018

FIR Submit Date: 04/05/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335680

Location Name: SGU-64S96W Number: 23SWSW County: \_\_\_\_\_

Qtrqr: SWS Sec: 23 Twp: 4S Range: 96W Meridian: 6  
W

Latitude: 39.681302 Longitude: -108.142770

FACILITY - API Number: 05-045- -00 Facility ID: 335680

Facility Name: SGU-64S96W Number: 23SWSW

Qtrqr: SWS Sec: 23 Twp: 4S Range: 96W Meridian: 6  
W

Latitude: 39.681302 Longitude: -108.142770

CORRECTIVE ACTIONS:

1 CA# 115659

Corrective Action: Reclaim Location for Interim Reclamation per COGCC 1003 Series Rules; installing Reclamation in areas no longer needed for Use, Production, Drilling or Subsequent Operations.

Date: 11/30/2018

Response: FACTUAL REVIEW REQUEST

Basis for Review: Action requested was already completed prior to the inspection

The M23 496 was interim reclaimed in October/November 2011. The location was reduced from its original footprint of 9.6 acres to 2.69 acres. The total area interim reclaimed was 6.91 acres. The associated google

Operator  
Comment: imagery (attached) shows the 2011 footprint (orange) and the 2015 footprint (green). The current operational footprint will be used for safe and adequate traffic flow, work over operations, and snow removal and storage. We believe that Caerus has met the intent of the regulation and believe that the M23 496 is in compliance with COGCC Rule 1003.b., "All disturbed areas affected by drilling or subsequent operations, except areas reasonably needed for production operations... shall be reclaimed as early and as nearly as practicable to their original condition or their final land use as designated by the surface owner and shall be maintained to control dust and minimize erosion to the extent practicable."

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 115660

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 04/20/2018

Response: CA COMPLETED

Date of Completion: 04/11/2018

Operator  
Comment: The BMPs along the access road are scheduled to be repaired.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Attention: Lou Colby

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lindsey Rider

Signed: \_\_\_\_\_

Title: EHS Lead

Date: 4/11/2018 1:35:12 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401604418	Google Earth Images 2011 - 2015
-----------	---------------------------------

Total Attach: 1 Files