

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/02/2018

Submitted Date:

04/05/2018

Document Number:

691300081**FIELD INSPECTION FORM**Loc ID 332855 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 88265Name of Operator: TIGGES OIL LLCAddress: 12406 WCR 64 1/2City: GREELEY State: CO Zip: 80631**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
TIGGES, KENNETH	970-686-2836	oakleylee@msn.com	
Kraich, Adam	970-420-0536	Adam.Kraich@state.co.us	(Area 117) Field Operations

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245631	WELL	PR	04/01/2016	OW	123-13426	LOG CABIN 1	PR

General Comment:

Location					
Lease Road:					
Type	Access				
comment:	Gated, Shares road with Noble Energy WPF IIIA18-13(123-13197).				
Corrective Action	L				Date:
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:	Verified 4/3/2018.				
Corrective Action:					Date: _____
Good Housekeeping:					
Type	WEEDS				
Comment:	Weeds growing up around wellhead and pumping unit.				
Corrective Action:	Comply with Rule 603.f .				Date: 05/05/2018
Type	UNUSED EQUIPMENT				
Comment:	Chemical drum appears unused, and has fallen off of stand at wellhead. See photos.				
Corrective Action:	Comply with Rule 603.f .				Date: 05/05/2018
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:					
Type: Ancillary equipment	# 1				corrective date
Comment:	Propane tank				
Corrective Action:					Date:
Type: Vertical Separator	# 1				
Comment:	With housing				
Corrective Action:					Date:
Type: Prime Mover	# 1				
Comment:	Electric motor				
Corrective Action:					Date:
Type: Prime Mover	# 1				
Comment:	Conventional pumping unit. Stuffing box appears to have been leaking at polish rod, resulting in stained wellhead equipment and soil. See photos.				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: 05/05/2018
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:	Placarding is missing on produced water tank, see photos.				
Corrective Action:	Install sign to comply with Rule 210.d.				Date: 05/05/2018

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berms with production tank.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.480792,-104.599711
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms at tank battery are starting to erode, consider maintenance to address future capacity and permeability concerns.			
	Berms are shared with produced water tank.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 245631 Type: WELL API Number: 123-13426 Status: PR Insp. Status: PR**Producing Well**Comment: [Production has not been reported since April, 2016.](#)Corrective Action: [Submit reports per rule 206.](#)Date: 05/05/2018**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401598814	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4426603
691300085	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4426594