

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2018

Submitted Date:

04/12/2018

Document Number:

690300255**FIELD INSPECTION FORM**

Loc ID 324069	Inspector Name: Spencer, Stan	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 1 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
2A Doc Num: _____			

Operator Information:			
OGCC Operator Number: <u>96850</u>			
Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u>			
Address: <u>PO BOX 370</u>			
City: <u>PARACHUTE</u>	State: <u>CO</u>	Zip: <u>81635</u>	

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Fischer, Alex		alex.fischer@state.co.us	
Lujan, Carlos		carlos.lujan@state.co.us	

General Comment:

Inspection prior to conversion from multi-well pit (F-15) to CE&P F-28 approval. Visible portion of pit liner has no apparent holes, tears or punctures. Pit volume ~1ft below capacity (3 ft total freeboard). Three small (<1'x1') patches visible on netting, no holes observed. Produced water in pit is dark stained and has petroleum odor but no free floating product observed. Multiple discharge pipes and hoses. External loadout station. Some pipes are in direct contact with liner on level surface above pit bank. Pit is in cut slope except for small section ~50' at SE corner which appears to be fill slope. Tank battery includes 2x500 bbl PW (gun barrel) 1x400 bbl PW (gun barrel) tank, 1x500 bbl sludge tank, and 3x300 bbl condensate tanks all within HDPE-lined steel SPCC.

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690300256	Inspection photos 3-11-18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4432418