

Inspection Photos
Location Name: CVR Pad 5-63-32
Location ID: 432011



Photo 1: Location, looking NE



Photo 2: Wellheads, looking SW

Inspection Photos
Location Name: CVR Pad 5-63-32
Location ID: 432011



Photo 3: Unlabeled tank



Photo 4: Stained soil at compressor

Inspection Photos
Location Name: CVR Pad 5-63-32
Location ID: 432011



Photo 5: Stained soil in separator house.



Photo 6: Stained soil at VRUs.

Inspection Photos
Location Name: CVR Pad 5-63-32
Location ID: 432011



Photo 7: Stained soil in separator house



Photo 8: Stained soil in separator house

Inspection Photos
Location Name: CVR Pad 5-63-32
Location ID: 432011



Photo 9: Stained soil in separator house



Photo 10: Stained soil near separator

Inspection Photos
Location Name: CVR Pad 5-63-32
Location ID: 432011



Photo 11: Stained soil at VRU.



Photo 12: Stained soil at VRU.

Inspection Photos
Location Name: CVR Pad 5-63-32
Location ID: 432011



Photo 13: Stained soil at engine oil container.



Photo 14: Stained soil at used engine oil container.

Inspection Photos
Location Name: CVR Pad 5-63-32
Location ID: 432011



Photo 15: Stained soil at compressor.



Photo 16: Stained soil at loadout.

Inspection Photos
Location Name: CVR Pad 5-63-32
Location ID: 432011



Photo 17: Stained soil near LACT.



Photo 18: Stained soil at container at LACT.