

Inspection Photos

Location Name: Staudinger 1-31H API: 05-123-34161

Inspection Date: 04/12/2018



Photo 1 – Location Sign



Photo 2 – Impacted soil beneath clean gravel at northwest corner of heater treater secondary containment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Staudinger 1-31H API: 05-123-34161

Inspection Date: 04/12/2018



Photo 3 – Northwest corner of heater treater secondary containment. Impacted soil in foreground.



Photo 4 – Impacted soil beneath clean gravel at southwest corner heater treater secondary containment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Staudinger 1-31H API: 05-123-34161

Inspection Date: 04/12/2018



**Photo 5 – Southwest corner of heater treater containment.
Impacted soil within containment.**



**Photo 6 – Northeast corner of heater treater containment
looking south.**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Staudinger 1-31H API: 05-123-34161

Inspection Date: 04/12/2018



Photo 7 – Wellhead area with unused rods and lube oil drum with no secondary containment.



Photo 8 – produced water AST showing release from thief hatch.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources