

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/13/2018

Submitted Date:

04/16/2018

Document Number:

689401140**FIELD INSPECTION FORM**Loc ID 312662 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Engineering		dnr_cogccengineering@state.co.us	All Engineering
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Reid, Jordan	(970) 563-4000	maralextechjr@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222107	WELL	SI	11/01/2014	GW	077-08709	SULFUR GULCH 9-98-2 1	SI

General Comment:

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable. This well is not listed in the Order 1V-609.

Location

Lease Road:			
Type	Access		
comment:	Seasonal conditions at low water crossing.		
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Sign not legible.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	06/16/2018

Emergency Contact Number:			
Comment:	Posted Emergency Contact Number 1-970-858-8550		
Corrective Action:		Date:	

Good Housekeeping:			
Type	WEEDS		
Comment:	Vegetation in tank containment.		
Corrective Action:	Comply with Rule 603.f.	Date:	05/16/2018

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 222107 Type: WELL API Number: 077-08709 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDSComment: Well last produced Oct 2014. MIT on 11/13/13.Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689401141	Sulfur Gulch 9-98-2 1 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4434757