

Inspection Photos

API: 05-067-06574

Operator: ENDURING RESOURCES LLC

Inspection Date: 3/21/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward. Vegetation is grazed and not in identifiable condition.



Photo 4. View of the western portion of the project area from the northwestern corner facing southward.



Photo 5. View of soil piles in the western project area. Cement debris, metal, and liner debris observed within the piles.



Photo 6. Closeup view of soil piles in the western project area and debris.